






















Assembly Instructions


1 Hardware List

	A	M6x35mm	18pcs		B	Ø 15x9mm	18pcs		C	Ø 6x30mm	28pcs
	D	M4x35mm	12pcs		E	M3.5x12mm	48pcs		F	M3.5x14mm	18pcs
	G		3pcs		H		3pcs		I		6pcs
	J		2pcs		K	M4x12mm	2pcs		L	Ø6x30mm	2pcs
	M	Ø20mm	10pcs		N	14x14x9mm	12pcs		O	M6x28mm	8pcs
	P	M6x40mm	4pcs		Q	4#	1pc				




2 Parts List

					
①	1pc	②	1pc	③	1pc
					
④	1pc	⑤	3pcs	⑥	1pc
					
⑦	1pc	⑧	2pcs	⑨	1pc
					
⑩	2pcs	⑪	2pcs	⑫	2pcs
					
⑬	1pc				





STEP 1

A -  × 2 F -  × 2 G1 -  × 1




STEP 2

C -  × 2 D -  × 2





STEP 3



B -  × 2 C -  × 2





STEP 4


A -  × 2 F -  × 2 G1 -  × 1



STEP 5 C -  x 2 D -  x 2




STEP 6 A -  x 4




STEP 7

B -  × 4 C -  × 4




STEP 8




STEP 9

A -  × 4




STEP 10

B -  × 4 C -  × 4




STEP 11


B -  × 2 C -  × 2




STEP 12




STEP 13 A -  x6 F -  x2 G1 -  x1 J -  x2 K -  x2



STEP 14 B -  x6 C -  x6 M -  x10




STEP 15




STEP 16

C -  x 6 D -  x 6




STEP 17

P -  x 4 Q -  x 1




STEP 18


O -  x 8 Q -  x 1





STEP 19


N -  x12 F -  x12



STEP 20 D -  x2 L -  x2




STEP 21 G2 -  x2 E -  x16 I -  x4 H -  x2





X2

STEP 22 G2 -  x1 E -  x8 I -  x2 H -  x1



STEP 23

E -  x24



STEP 24

