
















Assembly Instructions

1 Hardware List


	A	M6x35mm	8pcs		B	Ø15x10mm	8pcs		C	Ø6x30mm	16pcs
	D	M3.5x12mm	32pcs		E	M4x35mm	8pcs		F	M6x28mm	10pcs
	G	M6x40mm	4pcs		H		2pcs		I		4pcs
	J		4pcs		K		4pcs		L		2pcs
	M	M4*12mm	4pcs		N	M4mm	1pc		O		8pcs
	P	M3.5x14mm	4pcs								

2 Parts List


							
①	1pc	②	1pc	③	1pc	④	1pc
							
⑤	1pc	⑥	1pc	⑦	1pc	⑧	2pcs
							
⑨	1pc	⑩	2pcs	⑪	2pcs		




3




STEP 1 G -  x 4 N -  x 1




STEP 2 A - x 8 B - x 8 C - x 8





STEP 3 C - x 8 E - x 8




STEP 4 F - x 10 N - x 1




STEP 5 I - x 4 O - x 8



STEP 6 D - x28 H - x2 J - x4 L - x2 M - x4 P - x4



STEP 7 D - x4 K - x4



STEP 8

