


















Assembly Instructions


1 Hardware List

	A	M6x35mm	12pcs		B	Ø 15x9mm	12pcs		C	Ø 6x30mm	20pcs
	D	M4x35mm	10pcs		E	M3.5x12mm	32pcs		F	M3.5x14mm	12pcs
	G		2pcs		H		2pcs		I		4pcs
	J		2pcs		K	M4x12mm	2pcs		L	Ø6x30mm	2pcs
	M	Ø20mm	8pcs		N	14x14x9mm	8pcs		O	M6x28mm	8pcs
	P	M6x40mm	4pcs		Q	4#	1pc				




2 Parts List

					
①	1pc	②	1pc	③	1pc
					
④	1pc	⑤	2pcs	⑥	1pc
					
⑦	1pc	⑧	1pc	⑨	1pc
					
⑩	1pc	⑪	2pcs	⑫	2pcs





STEP 1

A -  × 2 F -  × 2 G1 -  × 1




STEP 2

C -  × 2 D -  × 2




STEP 3

B -  x 2 C -  x 2




STEP 4


A -  x 2



STEP 5 B -  × 2 C -  × 2




STEP 6 A -  × 2




STEP 7

B -  × 2 C -  × 2




STEP 8




STEP 9

A -  x6 F -  x2 G1 -  x1 J -  x2 K -  x2




STEP 10


B -  x6 C -  x6 M -  x8




STEP 11




STEP 12

C -  x 6 D -  x 6




STEP 13

P -  x 4 Q -  x 1




STEP 14



O -  x 8 Q -  x 1




STEP 15 N -  x8 F -  x8




STEP 16 D -  x2 L -  x2



STEP 17 G2 -  x1 E -  x8 I -  x2 H -  x1





STEP 18 G2 -  x1 E -  x8 I -  x2 H -  x1



STEP 19

E -  x16



STEP 20

